TO SHOULD BE SEEN OF SEEDING SEEDING	CLASSIFICATION	25X1
COUNTRY C	Approved For Release 2698/08/06 : CIA-RDP82-00457R01140	0 50009-4
	Aircraft Engine Repair Shop in Falkensee	25X1
11/11/O graphing and a	es COS estados estados estados atributados de la compansión de la compansi	Service to the Process State of the Service of the
EVALUATION_	25X1 PLACE CBTAINED.	25X1
DATE OF CONTENT. October and 1 to 18 December 1953		
DATE OBTAINED 25X1 25X1 DATE PREPARED 18 North 1952		
REFERENCES 25X1		
PAGESENCLOSURES (NO. & TYPE)		
REMARKS		
REMARKS.		
THE RESIDENCE AND PROPERTY OF THE PROPERTY OF		
ACMINISTRAÇÃO MINISTRAÇÃO DE LA VIENCIA PROPRESA	The second secon	T (20 ft of 2 - Benediction for the Visit of the Control of State (1985) (1985) (1985) (1985) (1985) (1985) (1985) (1985) (1985)
"affilianten en reten dinskrivetentrikk in pysigettiggere, solg, ungsv.o	THE REPORT OF THE PROPERTY OF	n district mind in materials of months in the second state of the second
25X1		
2. 25X1	and Leipziger Strasse. The depot was subordinate to the Prior to 1 December 1951, Captain Mintshuk (fnu) audited cember 1951, Mintshuk, who was meanwhile premoted to major shop again had a commanding officer, * The personnel in 60 Mi of the air force. Engine spare parts, tail and landing whools, and small a stored in the spare parts depoted the confidence of Cotober and the unloading of crates with in-line errors on 30 October 1951. The engines were brought to a V-type engines were stored. The units turn in engines is receive repaired or new engines which are hauled by true	of the bills. On 1 De- or, said that the repair necluded 30 officers and airframe parts were epair of radial engines engines from railroad storeroom in which 50 in need of repair and
25X1 3	On 17 December, a boxcar was shunted into the area.	7
25X1	Aircraft in-li	inc engines were being
25X1	unloaded. On 18 December, the following trucks and train a crate 2 x 2 x 3.5 meters, left the area	ilers, each loaded with
25X1 25X1		
25X1	Comment. Major Mintshuk was previously reported. Comment. This information confirms that an engine	repair shop is
25X1	located in Falkensee. Comment. The route Rosslau-Seddin-Austermark does not offer any leads.	
25X1	It is noteworthy that this route was previously reported	20
25X1		
	25X1	
CLASSIFICATION SECURE		